

42. Skivpallbrytning med långhål.  
100




FIGURE 72.8 The three operations involved in ring blasting, AECL (1980 a,b)




FIGURE 72.9 Sublevel stoping using fan patterns, Atlas Copco (1986)